

OnSight PROS Report

Professional Documentation

The attached report was produced by an OnSight PROS, LLC certified field technician and thus should not be confused with an inspection performed by a licensed real estate commission inspector. This report is an assessment of the condition of the property on the date shown and only the items listed in the report with notations made are reported on. Certified field technicians are not licensed to check the mechanicals, plumbing, or electrical units in a home and therefore this report will not reflect any issues or functionality of those components. This report is for the use of the property manager and/or owner to see first hand the condition of the property address as shown on the report. If no safety issues or deficiencies are observed, NO COMMENTS will be made.



REPORT DATE	PROPERTY LOCATION
11/4/2017	
REPORT TYPE	PROPERTY MANAGER
Move-in	

SERVICES PERFORMED	
ITEM	LOCATION
Basic Property Report	
Tenant Walkthrough & Signature	

NOTES

Air filter within specs. Wireless smoke alarms within specs. Minor wear and tear. Marks on walls. Kitchen sink leaking. Tears in vinyl flooring. Could not find water Shut Off. Electrical Panel in garage. Air filter in dining room closet in furnace.

SMELL TEST

Smell Test Performed. No exceptions noted.

SUMMARY OF ITEMS THAT NEED FURTHER EVALUATION

Front Exterior



Front Exterior
Driveway
Spider cracks in driveway.

Rear Exterior




Rear Exterior
Rear Gate
Does not lock fence properly.

Entry



Entry
Front Door Exterior
Dent in door.



Entry
Door Stops
Missing- no wall damage noted.


Living Room




Living Room FlooringTrim on floor not even.



Living Room Flooring Gap in flooring



Living Room Blinds/DrapesCurtain rod pulling away.



Living Room FireplaceFireplace key does not operate gas lever.

Kitchen



Kitchen Flooring Tear in floor.



Kitchen
Cabinet Under Sink
There is moisture present.


Garage




Garage Flooring Crack in flooring.




Garage Ceiling Cracks in ceiling.



Garage
Ceiling
Holes in ceiling.



Garage Walls/Paint Holes in wall.



Garage Walls/Paint Holes in wall.

OnSight PROS Report



Garage Walls/Paint Marks on walls.

Hallway/Stairway



Hallway/Stairway Flooring Stains in Flooring.



Hallway/Stairway Flooring Stains in Flooring.



Hallway/Stairway Walls/Paint Marks on walls.



Hallway/Stairway Walls/Paint Marks on wall.

Bedroom 1



Bedroom 1 Flooring Stains in Flooring.



Bedroom 1
Closets
The walls are marked up.

Bedroom 2



Bedroom 2 Walls/Paint Marks on wall.

Bedroom 3



Bedroom 3
Flooring
Carpet loose.



Bedroom 3 FlooringStains in Flooring.



Bedroom 3
Outlet/Switch Covers
Cover is missing.



Bedroom 3
Outlet/Switch Covers
Cover is missing.

Bathroom 2



Bathroom 2
Cabinet Under Sink
Discolored rear of cabinet.

Utility Room



Utility Room Flooring
Tear in floor.



Utility Room Walls/Paint Marks on wall.



Utility Room Washer Connection Faucets were leaking.

Miscellaneous



Miscellaneous Doorbell Makes a loud buzzing sound.

END OF SUMMARY OF ITEMS THAT NEED FURTHER EVALUATION

OnSight PROS Report

Front Exterior Observed Not Applicable Attention Needed

PROPERTY DETAIL

Front Exterior	Observed	Not Applicable	Attention Needed
1. Street Overview			
2. Center View			
3. Mail Box			
4. Roof/Trim/Gutter			
5. Driveway			×
6. Yard			
7. Front Left View			
8. Front Right View			
9. Walls/Siding/Trim			
10. Downspout/Splash Blocks			
11. Address			
12. Garage Door			
13. Sidewalks		N/A	
14. Landscaping			
15. Sprinkler System		N/A	
16. Window Screens			
17. Light Fixtures			
18. Other		N/A	

Front Exterior Observed Not Applicable Attention Needed



Street Overview



Mail Box



Driveway



Center View



Roof/Trim/Gutter



Driveway - Spider cracks in driveway.

Front Exterior Observed Not Applicable Attention Needed



Yard



Front Right View



Downspout/Splash Blocks



Front Left View




Walls/Siding/Trim



Address

Front Exterior Observed Not Applicable Attention Needed



Garage Door



Landscaping



Light Fixtures



Garage Door



Window Screens

OnSight PROS Report Observed Not Applicable Attention Needed **Rear Exterior** Rear Exterior Observed Not Applicable Attention Needed **/** X 1. Rear Gate 2. Overview 3. Roof/Trim/ Gutter 4. Walls/Siding/Trim 5. Downspout/ Splash Blocks 6. Window Screens 7. Yard 8. Landscaping 9. Patio/Porch 10. BBQ Grill 11. Tobacco Remains 12. Rear Door 13. Keyless Deadbolt/Pin Lock 14. Fence 15. Pet Evidence 16. Shed/ Storage Building 17. Insurance Risks 18. Light Fixtures 19. Sprinkler System 20. Pool Fence 21. Pool 22. Other

Rear Exterior Observed Not Applicable Attention Needed



Rear Gate



Overview



Walls/Siding/Trim



Rear Gate - Does not lock fence properly.



Roof/Trim/ Gutter



Downspout/ Splash Blocks

Rear Exterior Observed Not Applicable Attention Needed



Window Screens



Landscaping



Rear Door



Yard



Patio/Porch



Keyless Deadbolt/Pin Lock

Rear Exterior Observed Not Applicable Attention Needed



Fence



Fence



Insurance Risks



Fence



Shed/ Storage Building



Light Fixtures

Entry Observed Not Applicable Attention Needed

Entry Observed Not Applicable Attention Needed **/** 1. Porch/Patio 2. Front Door Exterior 3. Keyless Lock/Deadbolt 4. Peephole 5. Front Door Interior 6. Door Stops 7. Overview (Interior) 8. Floors 9. Ceiling 10. Walls/Paint 11. Outlet/Switch Covers 12. Light Fixtures 13. Other 14. Smoke Alarm





Porch/Patio Porch/Patio


Entry Observed Not Applicable Attention Needed




Front Door Exterior




Front Door Exterior - Dent in door.




Front Door Interior



Front Door Exterior




Keyless Lock/Deadbolt




Door Stops - Missing- no wall damage noted.

Entry Observed Not Applicable Attention Needed




Overview (Interior)




Ceiling



Outlet/Switch Covers



Floors




Walls/Paint

OnSight PROS Report

Living Room Observed Not Applicable Attention Needed

Living Room Observed Not Applicable Attention Needed **/** 1. Overview 2. Flooring 3. Ceiling 4. Walls/Paint 5. Door 6. Door Stops 7. Windows 8. Blinds/Drapes 9. Outlet/Switch Covers 10. Light Fixture 11. Ceiling Fan 12. Other 13. Smoke Alarm







Living Room Observed Not Applicable Attention Needed



Flooring - Trim on floor not even.




Ceiling



Walls/Paint



Flooring - Gap in flooring



Walls/Paint



Walls/Paint

Living Room Observed Not Applicable Attention Needed



Walls/Paint



Blinds/Drapes



Outlet/Switch Covers



Windows




Blinds/Drapes - Curtain rod pulling away.



Ceiling Fan


Living Room Observed Not Applicable Attention Needed




Fireplace - Fireplace key does not operate gas lever.

Dining Room	Observed	Not Applicable	Attention Needed
1. Overview			
2. Flooring			
3. Ceiling			
4. Walls/Paint			
5. Door Stops		N/A	
6. Windows		N/A	
7. Blinds/Drapes			
8. Outlet/Switch Covers			
9. Light Fixture			
10. Ceiling Fan		N/A	
11. Other		N/A	
12. Smoke Alarm		N/A	


Dining Room Observed Not Applicable Attention Needed



Overview




Ceiling



Walls/Paint



Flooring



Walls/Paint



Walls/Paint


OnSight PROS Report

Dining Room

Observed

Not Applicable


Attention Needed



Blinds/Drapes



Outlet/Switch Covers



Light Fixture

Kitchen	Observed	Not Applicable	Attention Needed
1. Overview			
2. Flooring			×
3. Ceiling			
4. Walls/Paint			
5. Sink/Faucet			
6. Cabinet Under Sink			X
7. Garbage Disposal		N/A	

OnSight PROS Report		,	_
Kitchen	Observed	Not Applicable	Attention Needed
8. Range/Cooktop/Oven MANUFACTURER: GE			
9. Oven		N/A	
10. Microwave Oven		N/A	
11. Dishwasher MANUFACTURER: GE			
12. Refrigerator MANUFACTURER: Whirlpool			
13. Lower Cabinets			
14. Counter Top/Back Splash			
15. Upper Cabinets			
16. Pantry			
17. Door Stops		N/A	
18. Windows			
19. Blinds/Drapes			
20. Outlet/Switch Covers			
21. Light Fixture			
22. Other		N/A	
23. Smoke Alarm		N/A	

Kitchen Observed Not Applicable Attention Needed



Overview




Flooring - Tear in floor.



Ceiling



Flooring



Ceiling



Walls/Paint

Kitchen Observed Not Applicable Attention Needed



Walls/Paint



Sink/Faucet



Cabinet Under Sink - There is moisture present.



Walls/Paint



Cabinet Under Sink



Range/Cooktop/Oven



Range/Cooktop/Oven



Dishwasher



Refrigerator



Dishwasher



Refrigerator



Lower Cabinets



Lower Cabinets



Lower Cabinets



Counter Top/Back Splash



Lower Cabinets



Counter Top/Back Splash



Upper Cabinets



Upper Cabinets



Upper Cabinets



Windows



Upper Cabinets



Pantry



Windows



Blinds/Drapes



Outlet/Switch Covers



Light Fixture



Blinds/Drapes



Light Fixture

OnSight PROS Report		,	
Garage	Observed	Not Applicable	Attention Needed
Garage	Observed	Not Applicable	Attention Needed
1. Door			
2. Door Stops			
3. Passage Door Keyless Locks/Deadbolt			
4. Overview			
5. Flooring			×
6. Ceiling			×
7. Walls/Paint			×
8. Garage Door			
9. Garage Door Sliding Locks			
10. Garage Door Electric Opener			
11. Windows			
12. Blinds/Drapes		N/A	
13. Outlet/Switch Covers			
14. Light Fixture			
15. Water Softener System		N/A	
16. Interior of Brine Tank		N/A	
17. Sprinkler Control		N/A	
18. Other		N/A	
19. Smoke Alarm		N/A	



Door




Passage Door Keyless Locks/Deadbolt - No deadbolt installed.



Flooring



Door Stops



Overview



Flooring - Crack in flooring.



Ceiling



Ceiling - Holes in ceiling.



Walls/Paint




Ceiling - Cracks in ceiling.



Walls/Paint



Walls/Paint



Walls/Paint - Holes in wall.




Walls/Paint - Marks on walls.



Garage Door




Walls/Paint - Holes in wall.



Garage Door



Garage Door Sliding Locks



Garage Door Sliding Locks



Garage Door Electric Opener



Outlet/Switch Covers



Garage Door Electric Opener



Windows



Light Fixture

OnSight PROS Report

Hallway/Stairway Observed Not Applicable Attention Needed


Hallway/Stairway Observed Not Applicable Attention Needed 1. Overview 2. Flooring 3. Ceiling 4. Walls/Paint 5. Closet 6. Outlet/Switch Covers 7. Light Fixture 8. Railings 9. Other 10. Smoke Alarm

ALARM TYPE: Wireless

MANUFACTURE DATE: May 2017

11/4/2017 1:26 PM

SMOKE ALARM TEST: Pass



Overview



Flooring

Hallway/Stairway

Observed Not Applicable Attention Needed



Flooring - Stains in Flooring.




Ceiling



Walls/Paint



Flooring - Stains in Flooring.



Walls/Paint



Walls/Paint - Marks on walls.

Hallway/Stairway

Observed Not Applicable Attention Needed



Walls/Paint - Marks on wall.




Outlet/Switch Covers



Smoke Alarm



Closet




Light Fixture




Smoke Alarm (DATE)

Hallway/Stairway Observed Not Applicable Attention Needed








Smoke Alarm (DATE)

Deduce and	01	No. (A P I.I.	Aller Con North
Bedroom 1	Observed	Not Applicable	Attention Needed
1. Overview			
2. Flooring			×
3. Ceiling			
4. Walls/Paint			
5. Door			
6. Door Stops			
7. Windows			
8. Blinds/Drapes			
9. Outlet/Switch Covers			
10. Light Fixture			
11. Ceiling Fan		N/A	
12. Closets			×
13. Other		N/A	
14. Smoke Alarm		N/A	

Bedroom 1 Observed Not Applicable Attention Needed



Overview



Flooring - Stains in Flooring.



Walls/Paint



Flooring



Ceiling



Walls/Paint

Bedroom 1 Observed Not Applicable Attention Needed



Walls/Paint



Door



Windows



Walls/Paint



Door Stops




Blinds/Drapes

Bedroom 1 Observed Not Applicable Attention Needed



Outlet/Switch Covers



Closets




Light Fixture



Closets - The walls are marked up.


Bedroom 2	Observed	Not Applicable	Attention Needed	
1. Overview				
2. Flooring				
3. Ceiling				
4. Walls/Paint			×	
5. Door				
6. Door Stops				
7. Windows				
8. Blinds/Drapes				




Bedroom 2 Observed Not Applicable Attention Needed




Walls/Paint



Walls/Paint



Door



Walls/Paint



Walls/Paint - Marks on wall.



Door Stops

Bedroom 2 Observed Not Applicable Attention Needed



Windows



Outlet/Switch Covers





Blinds/Drapes



Light Fixture

OnSight PROS Report

Bedroom 3 Observed Not Applicable Attention Needed

Bedroom 3 Observed Not Applicable Attention Needed **/** 1. Overview 2. Flooring 3. Ceiling 4. Walls/Paint 5. Door 6. Door Stops 7. Windows 8. Blinds/Drapes 9. Outlet/Switch Covers 10. Light Fixture 11. Ceiling Fan 12. Closets 13. Other 14. Smoke Alarm 11/4/2017 1:36 PM





Overview Flooring

Bedroom 3 Observed Not Applicable Attention Needed



Flooring - Carpet loose.



Ceiling



Walls/Paint



Flooring - Stains in Flooring.



Walls/Paint



Walls/Paint

Bedroom 3 Observed Not Applicable Attention Needed



Walls/Paint



Door Stops



Blinds/Drapes



Door



Windows



Outlet/Switch Covers - Cover is missing.

Bedroom 3 Observed Not Applicable Attention Needed



Outlet/Switch Covers - Cover is missing.



Ceiling Fan



Closets

Bathroom 1	Observed	Not Applicable	Attention Needed
1. Overview			
2. Flooring			
3. Ceiling			
4. Walls/Paint			
5. Sink/Faucet			
6. Cabinet Under Sink			
7. Commode			
8. Tub/Fixture			

OnSight PROS Report Bathroom 1 9. Shower/Fixture 10. Door 11. Door Stops 12. Towel Bars 13. Window 14. Blinds/Drapes

- 16. Light Fixtures17. Exhaust Fan
- 18. Closet
 19. Other
- 20. Smoke Alarm

15. Outlet/Switch Covers



Overview




Flooring

Bathroom 1 Observed Not Applicable Attention Needed



Ceiling



Walls/Paint



Cabinet Under Sink



Walls/Paint



Sink/Faucet




Commode

Bathroom 1 Observed Not Applicable Attention Needed



Tub/Fixture



Door



Outlet/Switch Covers



Shower/Fixture



Door Stops - Missing- no wall damage noted.



Light Fixtures

Bathroom 1 Observed Not Applicable Attention Needed



Exhaust Fan

Bathroom 2	Observed	Not Applicable	Attention Needed
1. Overview			
2. Flooring			
3. Ceiling			
4. Walls/Paint			
5. Sink/Faucet			
6. Cabinet Under Sink			×
7. Commode			
8. Tub/Fixture			
9. Shower/Fixture			
10. Door			
11. Door Stops			
12. Towel Bars		N/A	
13. Window			
14. Blinds/Drapes			
15. Outlet/Switch Covers			

OnSight PROS Report

Bathroom 2 Observed Not Applicable

- 16. Light Fixtures
- 17. Exhaust Fan
- 18. Closet
- 19. Other
- 20. Smoke Alarm



Overview



Ceiling



Attention Needed

Flooring



Walls/Paint

Bathroom 2 Observed Not Applicable Attention Needed



Walls/Paint



Cabinet Under Sink - Discolored rear of cabinet.



Tub/Fixture



Sink/Faucet



Commode



Shower/Fixture

Bathroom 2 Observed Not Applicable Attention Needed



Door



Window




Outlet/Switch Covers



Door Stops



Blinds/Drapes




Light Fixtures

OnSight PROS Report

Utility Room Observed Not Applicable Attention Needed

Utility Room Observed Not Applicable Attention Needed **/** 1. Overview 2. Flooring 3. Ceiling 4. Walls/Paint 5. Washer Connection 6. Washing Machine 7. Dryer 8. Door 9. Door Stops 10. Window 11. Blinds/Drapes 12. Outlet/Switch Covers 13. Light Fixtures 14. Other 15. Smoke Alarm







Flooring

Utility Room Observed Not Applicable Attention Needed



Flooring - Tear in floor.




Walls/Paint



Washer Connection - Faucets were leaking.



Ceiling



Walls/Paint - Marks on wall.



Door

Utility Room Observed Not Applicable Attention Needed



Outlet/Switch Covers

Miscellaneous	Observed	Not Applicable	Attention Needed
1. Air Conditioner			
2. Satellite Dish			
3. Thermostat			
4. Fire Extinguisher		N/A	
5. House Keys/Qty			
6. Garage Remotes/Qty			
7. Mailbox Keys/Qty			
8. Security System			
9. Water Heater TYPE: Gas MANUFACTURER: GE			
10. Carbon Monoxide Detector		N/A	
11. AC Filter FILTER CONDITION: Filter very recently replaced. Little or no dust observed. FILTER SIZE: 14x25x1			
12. AC Filter 2		N/A	
13. AC Filter 3		N/A	

OnSight PROS Report

Miscellaneous Observed Not Applicable Attention Needed

- 14. Pet Evidence
- 15. Trip Hazards
- 16. Drainage Issues
- 17. Other



Air Conditioner



Thermostat



N/A

Satellite Dish



House Keys/Qty

Miscellaneous Observed Not Applicable Attention Needed



Garage Remotes/Qty



Security System



Water Heater



Mailbox Keys/Qty



Water Heater



AC Filter - FILTER CONDITION: Filter very recently replaced. Little or no dust observed.

OnSight PROS Report

Miscellaneous Observed Not Applicable Attention Needed



AC Filter



Electrical Panel



AC Filter



Doorbell - Makes a loud buzzing sound.

END OF PROPERTY DETAIL

SIGNATURES

TENANT SIGNATURE

TECHNICIAN SIGNATURE

End of Report